

Year 7 Annual Report
Massachusetts Small MS4 General Permit
Reporting Period: July 1, 2024-June 30, 2025

Please DO NOT attach any documents to this form. Instead, attach all requested documents to an email when submitting the form. Also ensure any websites included on this form are to publicly accessible sites

Unless otherwise noted, all fields are required to be filled out. If a field is left blank, it will be assumed the requirement or task has not been completed. Please ONLY report on activities between July 1, 2024 and June 30, 2025 unless otherwise requested.

Part I: Contact Information

Name of Municipality or Organization:

EPA NPDES Permit Number:

Primary MS4 Program Manager Contact Information

Name: Title:

Street Address Line 1:

Street Address Line 2:

City: State: Zip Code:

Email: Phone Number:

Stormwater Management Program (SWMP) Information

SWMP Location (publicly available web address):

Date SWMP was Last Updated:

If the SWMP is not available on the web please provide the physical address:

Part II: Self-Assessment

First, in the box below, select the impairment(s) and/or TMDL(s) that are applicable to your MS4. Make sure you are referring to the most recent EPA approved Section 303(d) Impaired Waters List which can be found here: <https://www.epa.gov/tmdl/region-1-impaired-waters-and-303d-lists-state>

Impairment(s)

Bacteria/Pathogens Chloride Nitrogen Phosphorus
 Solids/ Oil/ Grease (Hydrocarbons)/ Metals

TMDL(s)

In State: Assabet River Phosphorus Bacteria and Pathogen Cape Cod Nitrogen
 Charles River Watershed Phosphorus Lake and Pond Phosphorus

Out of State: Bacteria/Pathogens Metals Nitrogen Phosphorus

Clear Impairments and TMDLs

Next, check off all requirements below that have been completed. **By checking each box you are certifying that you have completed that permit requirement fully.** If you have not completed a requirement leave the box unchecked. Additional information will be requested in later sections.

Year 7 Requirements

- Completed catchment investigations associated with Problem Outfalls
- Completed catchment investigations where information gathered on the outfall/interconnection indicated sewer input

Annual Requirements

- Provided an opportunity for public participation in review and implementation of SWMP and complied with State Public Notice requirements
- Kept records relating to the permit available for 5 years and made available to the public
- The SSO inventory has been updated, including the status of mitigation and corrective measures implemented
 - This is not applicable because we do not have sanitary sewer
 - This is not applicable because we did not find any new SSOs
 - The updated SSO inventory is attached to the email submission
 - The updated SSO inventory can be found at the following publicly available website:

- Updated system map due in year 10 with information from completed catchment investigations
- Provided training to employees involved in IDDE program within the reporting period
- Properly stored and disposed of catch basin cleanings and street sweepings so they did not discharge to receiving waters

- All curbed roadways were swept at least once within the reporting period
- Enclosed all road salt storage piles or facilities and implemented winter road maintenance procedures to minimize the use of road salt
- Implemented SWPPPs for all permittee owned or operated maintenance garages, public works yards, transfer stations, and other waste handling facilities
- Updated inventory of all permittee owned facilities as necessary
- O&M programs for all permittee owned facilities have been completed and updated as necessary
- Implemented all maintenance procedures for permittee owned facilities in accordance with O&M programs
- Implemented program for MS4 infrastructure maintenance to reduce the discharge of pollutants
- Inspected all permittee owned treatment structures (excluding catch basins)

Optional: If you would like to describe progress made on any incomplete requirements listed above or provide any additional details, please use the box below:

The Town does not have any Problem outfall catchments.

The Town does not have any outfalls that met the MS4 permit's criteria for likely sewer input. However, the Town has 1 outfall that was categorized as high priority based on indicators of potential illicit connections from the dry weather outfall screening. Catchment investigations for this outfall are in progress but not yet completed. This will be prioritized for Permit Year 8 investigations.

The Town's Municipal Good Housekeeping and Pollution Prevention Program includes maintenance procedures for Town facilities and MS4 infrastructure, which are implemented to the maximum extent practicable. Maintenance was performed as needed for MS4 infrastructure in Permit Year 7.

Bacteria/ Pathogens (Combination of Impaired Waters Requirements and TMDL Requirements as Applicable)

Annual Requirements

*Public Education and Outreach**

- Annual message was distributed encouraging the proper management of pet waste, including noting any existing ordinances where appropriate
- Permittee or its agents disseminated educational material to dog owners at the time of issuance or renewal of dog license, or other appropriate time
- Provided information to owners of septic systems about proper maintenance in any catchment that discharges to a water body impaired for bacteria
 - This is not applicable because there are no septic systems present

** Public education messages can be combined with other public education requirements as applicable (see Appendix F and H for more information)*

Optional: If you would like to describe progress made on any incomplete requirements listed above or provide any additional details, please use the box below:

Although pet waste education is not distributed with dog licenses, a Think Blue Massachusetts brochure entitled "Do Your 'Doody' for Clean Water", which highlights proper management of pet waste, is included on the Town's Stormwater Management webpage and is readily available to residents. The Town is also considering adding education to the Dog Licenses webpage (<https://www.webster-ma.gov/326/Dog-Licenses>).

Nitrogen (Combination of Impaired Waters Requirements and TMDL Requirements as Applicable)**Annual Requirements***Public Education and Outreach**

- Distributed an annual message in the spring (April/May) that encourages the proper use and disposal of grass clippings and encourages the proper use of slow-release fertilizers
- Distributed an annual message in the summer (June/July) encouraging the proper management of pet waste, including noting any existing ordinances where appropriate
- Distributed an annual message in the fall (August/September/October) encouraging the proper disposal of leaf litter

** Public education messages can be combined with other public education requirements as applicable (see Appendix F and H for more information)*

Good Housekeeping and Pollution Prevention for Permittee Owned Operations

- Increased street sweeping frequency of all municipal owned streets and parking lots subject to Permit part 2.3.7.a.iii.(c) to a minimum of two times per year (spring and fall)

Structural BMPs

- Installed a structural BMP as a demonstration project within the drainage area of the water quality limited water or its tributaries. The type of BMP installed is (e.g. *biofiltration*):

Underground infiltration system and 2 detention basins were installed at the Bartlett High School, as noted in Permit Year 6 annual report. The rest of the site construction is still underway. When construction is completed, public education about the project will be posted on the Town's webpage and News Blast.

Any structural BMPs listed in Attachment 3 to Appendix F already existing or installed in the regulated area by the permittee or its agents was tracked and the nitrogen removal by the BMP was estimated

- consistent with Attachment 3 to Appendix F. The BMP type, total area treated by the BMP, the design storage volume of the BMP, and the estimated nitrogen removed in mass per year by the BMP were documented.


- No BMPs were installed
- The above referenced BMP information is attached to the email submission
- The above referenced BMP information can be found at the following publicly available website:

No new Town-owned BMPs were installed in Permit Year 7. The nitrogen removal estimate was submitted with the Permit Year 6 annual report.

Total estimated nitrogen removed in lbs/year from the installed BMPs: 82.6

Optional: If you would like to describe progress made on any incomplete requirements listed above or provide any additional details, please use the box below:

Optional: Use the box below to provide any additional information you would like to share as part of your self-assessment:

A large, empty rectangular box with a thin black border, intended for the respondent to write any additional information they would like to share as part of their self-assessment.

Part III: Receiving Waters/Impaired Waters/TMDL

Have you made any changes to your lists of receiving waters, outfalls, or impairments since the NOI was submitted?

- Yes
- No

If yes, describe below, including any relevant impairments or TMDLs:

The Town's NOI listed receiving waters and impairments based on the water quality limited waters in the 2014 303(d) Integrated List. The Town evaluated changes to the impairments and/or receiving waters based on the final 2016 303(d) Integrated List and the analysis was included in the Town's Permit Year 2 Annual Report and is available in the SWMP. The Town evaluated changes to the impairments and/or receiving waters based on the final 2018/2020 303(d) Integrated List and the analysis was included in the Town's Permit Year 4 Annual Report and is available in the SWMP. In Permit Year 5, the Town evaluated any changes to the impairments and/or receiving waters based on the final 2022 303(d) List and included the analysis in the Permit Year 5 Annual Report and is available in the SWMP. The changes described do not add, remove, or change any receiving waters.

During Permit Year 7, the following updates were made to the Town's outfall inventory:

- 17 outfalls were added when discovered in the field during catchment investigations;
- 25 outfalls were removed as they were found to not exist, were misclassified stormwater assets (BMP inlets, culverts), or privately owned.
- 1 outfall was added back into the inventory when it was discovered it was incorrectly removed in a previous permit year.

These modifications do not add, remove, or change any receiving waters.

Part IV: Minimum Control Measures

Please fill out all of the metrics below. If applicable, include in the description who completed the task if completed by a third party.

MCM1: Public Education

Number of educational messages completed **during this reporting period:** 6

*Below, report on the educational messages completed **during this reporting period**. For the measurable goal(s) please describe the method/measures used to assess the overall effectiveness of the educational program.*

BMP: Public Education and Outreach to Residents (Stormwater Management Website)

Message Description and Distribution Method:

The Town's Stormwater webpage contains links to the following key documents under their stormwater management plan:

- The Town's Stormwater Management Game Plan
- The Town's Stormwater Management Plan
- The Town's Stormwater Management By-Law
- The Town's Stormwater Permit Application
- The Town's Wetlands Protection By-Law
- Annual Reports (Years 1-6)

Under the "Learn More" tab, the webpage also includes infographics titled:

- "Do Your Doody for Clean Water"

Elsewhere on the page is more public education and informational materials for residents:

- "The Scoop on Stormwater" (An EPA video)
- Small articles entitled "What is Stormwater?", "Why Stormwater Management?", and "Stormwater and Wastewater Are Not the Same!"
- "After the Storm - A Citizen's Guide to Understanding Stormwater"
- "MassDEP Stormwater Information"
- "FEMA for Kids"
- "EPA Environmental Kids Club"
- "NOAA for Kids - The Ocean"

Targeted Audience: Residents

Responsible Department/Parties: Planning Department

Measurable Goal(s):

All visitors to the webpage are able to view and download these educational materials. During the reporting year, the Town's webpage had 311 visitors.

Message Date(s): Ongoing

Message Completed for: Appendix F Requirements Appendix H Requirements

Was this message different than what was proposed in your NOI? Yes No

If yes, describe why the change was made:

BMP:Public Education and Outreach to Developers (Stormwater Management Website)

Message Description and Distribution Method:

In addition to the links to the Stormwater Management By-law, Wetlands Protection By-law, and Stormwater Permit Application, the Town's Stormwater webpage contains links to the following educational materials tailored to developers under their stormwater management plan:

- "Stop Erosion in its Tracks"
- "Plan Ahead...Prevent Pollution"

Targeted Audience: Developers (construction)

Responsible Department/Parties: Planning Department

Measurable Goal(s):

All visitors to the webpage are able to view and download these educational materials. During the reporting year, the Town's webpage had 311 visitors.

Message Date(s): Ongoing

Message Completed for: Appendix F Requirements Appendix H Requirements

Was this message different than what was proposed in your NOI? Yes No

If yes, describe why the change was made:

BMP: Public Education and Outreach to Industrial Facilities (Stormwater Management Website)

Message Description and Distribution Method:

The Town's Stormwater webpage contains links to the following educational materials tailored to industrial facilities under their stormwater management plan:

- "Put Hazards in Their Place"
- "Know the Drill for Spills"
- "Gas, Oil and Grease...Oh My!"

Targeted Audience: Industrial facilities

Responsible Department/Parties: Planning Department

Measurable Goal(s):

All visitors to the webpage are able to view and download these educational materials. During the reporting year, the Town's webpage had 311 visitors.

Message Date(s): Ongoing

Message Completed for: Appendix F Requirements Appendix H Requirements

Was this message different than what was proposed in your NOI? Yes No

If yes, describe why the change was made:

BMP: Public Education and Outreach to Residents (Social Media)

Message Description and Distribution Method:

The Town had made a few informational posts on their Facebook page related to water quality for their residents:

- The Town shared multiple posts informing of temporary water service interruptions, water main breaks, and mandatory drought restrictions.
- The Town shared multiple posts about road closings.

Targeted Audience: Residents

Responsible Department/Parties: Planning Department, Town of Webster

Measurable Goal(s):

These posts are available to the Town's 5,600 Facebook followers.

Message Date(s): July 1, 2024- June 30, 2025

Message Completed for: Appendix F Requirements Appendix H Requirements

Was this message different than what was proposed in your NOI? Yes No

If yes, describe why the change was made:

BMP: Public Education and Outreach to Businesses (Stormwater Management Website)

Message Description and Distribution Method:

The Town's Stormwater webpage contains links to the following educational materials tailored to businesses under their stormwater management plan:

- "Put Waste in its Place"
- "One Parking Lot at a Time"
- "Gas, Oil and Grease...Oh My!"

Targeted Audience: Businesses, institutions and commercial facilities

Responsible Department/Parties: Planning Department

Measurable Goal(s):

All visitors to the webpage are able to view and download these educational materials. During the reporting year, the Town's webpage had 311 visitors.

Message Date(s): Ongoing

Message Completed for: Appendix F Requirements Appendix H Requirements

Was this message different than what was proposed in your NOI? Yes No

If yes, describe why the change was made:

BMP: Public Education and Outreach to Residents (Health Department Webpage)

Message Description and Distribution Method:

The Town's Health Department has a link to the EPA's "SepticSmart" webpage, with informational material on septic systems and proper maintenance.

Targeted Audience: Residents

Responsible Department/Parties: Health Department

Measurable Goal(s):

All visitors to the webpage are able to follow the link to the educational materials. During the reporting year, the Town's webpage had 1,124 visitors.

Message Date(s): Ongoing

Message Completed for: Appendix F Requirements Appendix H Requirements

Was this message different than what was proposed in your NOI? Yes No

If yes, describe why the change was made:

[Add an Educational Message](#)

MCM2: Public Participation

Describe the opportunity provided for public involvement in the development of the Stormwater Management Program (SWMP) **during this reporting period**:

The Town's SWMP was posted on the Town's website and is available for public review. Comments can be provided via phone call or through a linked Department Contact Form.

Was this opportunity different than what was proposed in your NOI? Yes No

Describe any other public involvement or participation opportunities conducted **during this reporting period:**

The planned Earth Day cleanup on April 26, 2025, was canceled due to weather. However, green bags were available for pick up at the Highway Department, and an additional trash pickup was scheduled during the week. Approximately 20-25 bags were collected.

The Town's compost facility opened for the spring on April 7, 2025. 195 residents bought stickers.

MCM3: Illicit Discharge Detection and Elimination (IDDE)

Sanitary Sewer Overflows (SSOs)

Check off the box below if the statement is true.

This SSO section is NOT applicable because we DO NOT have sanitary sewer

*Below, report on the number of SSOs identified in the MS4 system and removed **during this reporting period**.*

Number of SSOs identified:

Number of SSOs removed:

MS4 System Mapping

Percent of Phase II map complete:

Optional: Provide additional status information regarding your map:

The Phase II mapping percentage was determined using the Town's completed catchment investigation percentage where the Phase II mapping has been field verified. This percentage is a conservative estimate since the Town has a robust stormwater GIS database within the MS4 with 231 outfalls, 2,334 catch basins, 780 manholes, and nearly 2,000 drainage pipes (equating to approximately 29.8 miles of pipeline) mapped. The Town plans on continuing to confirm the completeness of its Phases II mapping during the Town's catchment investigation efforts. This percentage will be continuously updated in upcoming permit years.

Screening of Outfalls/Interconnections

If conducted, please submit any outfall monitoring results from this reporting period. Outfall monitoring results should include the date, outfall/interconnection identifier, location, weather conditions at time of sampling, precipitation in previous 48 hours, field screening parameter results, and results from all analyses. Please also include the updated inventory and ranking of outfalls/interconnections based on monitoring results.

- No outfalls were inspected
- The above referenced outfall screening data is attached to the email submission
- The above referenced outfall screening data can be found at the following publicly available website:

*Below, report on the number of outfalls/interconnections screened **during this reporting period**.*

Number of outfalls screened: 16

*Below, report on the percent of outfalls/interconnections screened **to date**.*

Percent of outfalls screened: 99

Optional: Provide additional information regarding your outfall/interconnection screening:

As catchment investigation fieldwork was completed, two new outfalls were discovered to have dry weather flow and sampling will be completed in Permit Year 8.

Catchment Investigations

If conducted, please submit all data collected during this reporting period as part of the dry and wet weather investigations. Also include the presence or absence of System Vulnerability Factors for each catchment.

- No catchment investigations were conducted
- The catchment investigation data is attached to the email submission
- The catchment investigation data can be found at the following publicly available website:

[Redacted]

*Below, report on the number of catchment investigations completed **during this reporting period**.*

Number of catchment investigations completed this reporting period: 25

*Below, report on the percent of catchments investigated **to date**.*

Percent of total catchments investigated: 21

Optional: Provide any additional information for clarity regarding the catchment investigations below:

[Redacted]

IDDE Progress

If illicit discharges were found, please submit a document describing work conducted over this reporting period, and cumulative to date, including location source; description of the discharge; method of discovery; date of discovery; and date of elimination, mitigation, or enforcement OR planned corrective measures and schedule of removal.

- No illicit discharges were found
- The illicit discharge removal report is attached to the email submission
- The illicit discharge removal report can be found at the following publicly available website:

[Redacted]

*Below, report on the number of illicit discharges identified and removed, along with the volume of sewage removed **during this reporting period**.*

Number of illicit discharges identified: 0

Number of illicit discharges removed: 0

Estimated volume of sewage removed: 0 gallons/day

Below, report on the total number of illicit discharges identified and removed to date. At a minimum, report on the number of illicit discharges identified and removed since the effective date of the permit (July 1, 2018).

Total number of illicit discharges identified: 0

Total number of illicit discharges removed: 0

Optional: Provide any additional information for clarity regarding illicit discharges identified, removed, or planned to be removed below:

Employee Training

Describe the frequency and type of employee training conducted **during this reporting period**:

Highway staff conducted 3 days of IDDE field work with their stormwater consultant, providing on-the-job refresher training on outfall and catchment investigation practices. Monthly meetings are held with all Highway Department staff that review safety and road work precautions, as well as identifying illicit discharges at stormwater outfalls, and catch basin cleanings.

MCM4: Construction Site Stormwater Runoff Control

*Below, report on the construction site plan reviews, inspections, and enforcement actions completed **during this reporting period**.*

Number of site plan reviews completed: 24

Number of inspections completed: 55

Number of enforcement actions taken: 3

Optional: Enter any additional information relevant to construction site plan reviews, inspections, and enforcement actions:

Two new private BMPs were installed this year at 118-120 Thomspson Rd and 137 E Main St.

MCM5: Post-Construction Stormwater Management in New Development and Redevelopment

As-built Drawings

*Below, report on the number of as-built drawings received **during this reporting period**.*

Number of as-built drawings received: 3

Optional: Enter any additional information relevant to the submission of as-built drawings:

Street Design and Parking Lots Report

Below, describe any changes made or planned to be made to local regulations and guidelines based on the report completed in Year 4:

The Local Code Assessment completed in June 2023 and revised April 2024 recommended updates to Subdivision Regulations (in July 2025) and Zoning Bylaw (in July 2026). The Town is currently working on updating the Stormwater Regulations and plans to revisit the plan/schedule for other code updates once the Stormwater Regulations are adopted.

Green Infrastructure Report

Below, describe progress towards making green infrastructure practices allowable based on the report completed in Year 4:

The Local Code Assessment completed in June 2023 and revised April 2024 recommended updates to Subdivision Regulations (in July 2025) and Zoning Bylaw (in July 2026). The Town is currently working on updating the Stormwater Regulations and plans to revisit the plan/schedule for other code updates once the Stormwater Regulations are adopted.

Retrofit Properties Inventory

Below, list remaining permittee-owned properties that could be modified or retrofitted with BMPs to mitigate impervious areas (must maintain a minimum of 5 sites in inventory until less than 5 sites remain):

Public Safety Complex/Fire
Highway and Transfer Station
William S. Slater Playground & Lassie League Field

Emergency Medical Services
Memorial Park / Memorial Athletic Fields

Below, list all properties that have been modified or retrofitted with BMPs to mitigate impervious area that were inventoried as part of 2.3.6.d of the permit and the type of BMP(s) implemented. Non-MS4 owned properties that have been modified or retrofitted with BMPs to mitigate impervious area may also be listed, but must be indicated as non-MS4.

Bartlett High School - The existing high school was renovated, which included removal of excess building square footage (overall square footage of the building was reduced by creating new courtyards). The work included a new parking layout and new utilities, which consisted of stormwater management infrastructure improvements and reconfiguration. This added water quality units, an underground infiltration system, and 2 detention basins.

MCM6: Good Housekeeping

Catch Basin Cleaning

*Below, report on the number of catch basins inspected and cleaned, along with the total volume of material removed from the catch basins **during this reporting period**.*

Number of catch basins inspected:

Number of catch basins cleaned:

Total volume or mass of material removed from all catch basins: cubic yards

Below, report on the total number of catch basins in the MS4 system.

Total number of catch basins:

If applicable:

Report on the actions taken if a catch basin sump is more than 50% full during two consecutive routine inspections/cleaning events:

Catch basins are inspected when they are cleaned. Additional catch basins were inspected throughout the year during catchment investigations as well as during construction and to ensure they were functioning. Due to staffing and budgeting constraints, not all catch basins are cleaned every year.

Street Sweeping

*Report on street sweeping completed **during this reporting period** using one of the three metrics below.*

Number of miles cleaned:

Volume of material removed:

Weight of material removed:

Stormwater Pollution Prevention Plan (SWPPP)

*Below, report on the number of site inspections for facilities that require a SWPPP completed **during this reporting period**.*

Number of site inspections completed:

Describe any corrective actions taken at a facility with a SWPPP:

N/A

Additional Information

Monitoring or Study Results

Results from any other stormwater or receiving water quality monitoring or studies conducted during the reporting period not otherwise mentioned above, where the data is being used to inform permit compliance or permit effectiveness must be attached.

Not applicable

The results from additional reports or studies are attached to the email submission

The results from additional reports or studies can be found at the following publicly available website(s):

If such monitoring or studies were conducted on your behalf or if monitoring or studies conducted by other entities were reported to you, a brief description of the type of information gathered or received shall be described below:

Additional Information

Enter any additional information relevant to your stormwater management program implementation during the reporting period. Include any BMP modifications made by the MS4 if not already discussed above.

Year 8

Activities Planned for Next Reporting Period

Please confirm that your SWMP has been, or will be, updated to comply with all applicable permit requirements including but not limited to the year 8 requirements summarized below. (Note: impaired waters and TMDL requirements are not listed below)

Yes, I agree

Annual Requirements

- Annual report submitted and available to the public
- Annual opportunity for public participation in review and implementation of SWMP
- Keep records relating to the permit available for 5 years and make available to the public
- Properly store and dispose of catch basin cleanings and street sweepings so they do not discharge to receiving waters
- Annual training to employees involved in IDDE program
- Update inventory of all known locations where SSOs have discharged to the MS4
- Continue public education and outreach program
- Update outfall and interconnection inventory and priority ranking and include data collected in connection with the dry weather screening and other relevant inspections conducted
- Implement IDDE program
- Review site plans of construction sites as part of the construction stormwater runoff control program
- Conduct site inspection of construction sites as necessary
- Inspect and maintain stormwater treatment structures
- Log catch basins cleaned or inspected
- Sweep all curbed streets at least annually
- Continue investigations of catchments associated with Problem Outfalls
- Implemented SWPPPs for all permittee owned or operated maintenance garages, public works yards, transfer stations, and other waste handling facilities
- Review inventory of all permittee owned facilities in the categories of parks and open space, buildings and facilities, and vehicles and equipment; update if necessary
- Review O&M programs for all permittee owned facilities; update if necessary
- Implement all maintenance procedures for permittee owned facilities in accordance with O&M programs
- Implement program for MS4 infrastructure maintenance to reduce the discharge of pollutants
- Enclose all road salt storage piles or facilities and implemented winter road maintenance procedures to minimize the use of road salt
- Review as-built drawings for new and redevelopment to ensure compliance with post construction bylaws, regulations, or regulatory mechanism consistent with permit requirements
- Inspect all permittee owned treatment structures (excluding catch basins)
- Identify additional permittee-owned properties that could potentially be modified or retrofitted

with BMPs to reduce impervious areas so that the permittee maintains a minimum of 5 sites in their inventory, until such a time when the permittee has less than 5 sites remaining

Provide any additional details on activities planned for permit year 8 below:

The Town acknowledges the General Permit Year 8 requirements and will complete as many activities as possible based on funding and staff availability.

Part V: Certification of Small MS4 Annual Report 2025

40 CFR 144.32(d) Certification

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, I certify that the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Name:

Richard LaFond

Title:

Town Adminstrator

Signature:

Date:

*[Signatory may be a duly authorized
representative]*